



1. Tracker Ball
2. Screen
3. Hydrocarbon Scrubber
4. On/Off Button
5. USB 2.0 Port
6. Scrubber Inlet
7. ATLAS Pneumatic Control Box
8. Stirrer Speed Increase/Decrease
9. Stirrer Display
10. Stir-bar Capture Button
11. Stirring Mode Selector
12. Pressure Gauge
13. Pressure Regulator
14. Pressure Adjustment Dial
15. Gas Toggle Valve
16. ATLAS Heater Control Box
17. Temperature Status Indicator
18. On/Off Switch
19. Power Indicator
20. Cable to Sample Stirrer Module
21. Sample Stirrer Module
22. Exhaust From Lonestar
23. Filter Block
24. Sample Holder
25. Heated Lid/Filter Regions
26. Sample Flow
27. Make-up Flow
28. Split Flow
29. Clean Air Supply
30. Air Supply Inlet
31. Exhaust from ATLAS Pneumatic Control Box
32. Power Supply
33. Stirrer Control Port
34. Stirrer Communication Port
35. Stirrer On/Off Switch
36. Supply Voltage Selector
37. Mains Socket
38. Fuse
39. T1, T2, T3 Ports
40. Thermocouple
41. ATLAS Heater Control Box Communications Port
42. Fuse
43. Power Supply Socket